

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

**** SBFCA currently has operation and maintenance obligations during project construction and closeout.**

Sutter Maintenance Yard Maintenance Area 0016

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	4.06	09/08/2016 09/08/2016	Sterling York

LM Start		Rating **	A	Issue No.	3
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_MA0016_01_s _ 2013_3				
Comment Code					
Inspector Comment					
There will be new O&M manuals when the levee is turned back over to the LMA after construction is complete. The O&M manuals are located at the Sutter Maintenance Yard.					

No Photos

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_MA0016_01_s _ 2013_4				
Comment Code					
Inspector Comment					
Sutter maintenance yard employees attend the annual Flood Fight class put on by DWR inspector Bob Duffy.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

**** SBFCA currently has operation and maintenance obligations during project construction and closeout.**

Sutter Maintenance Yard Maintenance Area 0016

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	4.06	09/08/2016 09/08/2016	Sterling York

LM Start		Rating **	A	Issue No.	5	
LM End		Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Emergency Supplies & Equipment				°	
					°	
DWR ID	DWR_MA0016_01_s_2013_5					
Comment Code						
Inspector Comment						
Emergency supplies and equipment are stored at the Sutter Maintenance Yard.						

No Photos

LM Start	3.19	Rating **	M	Issue No.	10
LM End	3.65	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.298312 °	39.305053 °
				-121.638327 °	-121.637729 °
DWR ID	DWR_MA0016_01_f_2016_10				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual grasses that need to be maintained.					

Photo 1 of 1 : FA_2016_MA0016_302_10_20160912_00013.jpg



View looking downstream, landside, of annual grasses that need to be maintained.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

**** SBFCA currently has operation and maintenance obligations during project construction and closeout.**

Sutter Maintenance Yard Maintenance Area 0016

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	4.06	09/08/2016 09/08/2016	Sterling York

LM Start	3.19	Rating **	M	Issue No.	9
LM End	3.81	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.298312°	39.307293°
				-121.638328°	-121.637671°
DWR ID	DWR_MA0016_01_f_2016_9				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual grasses that need to be maintained.					

Photo 1 of 1 : FA_2016_MA0016_302_9_20160912_00012.jpg



View looking downstream, waterside, of annual grasses that need to be maintained.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---